



APPLIED TECHNICAL SERVICES, INCORPORATED

1049 Triad Court, Marietta, Georgia 30062 • (770) 423-1400 Fax (770) 424-6415

CHEMICAL TEST REPORT

Ref. C257277

Date July 25, 2016

Page 1 of 1

Customer: Jacob Olssen, 1121 Olympic Dr., Corona, CA 92881

Attention: Jacob Olssen

Purchase Order #: CC

Part #/Name: Yosemite Vinyl Plank 8399

Material Designation: N/A

Special Requirement: N/A

Lab Comment: GC/MS was used to identify and quantify the phthalate compounds according to CPSC-CH-C1001-09.3 Consumer Product Safety Commission's Standard Operating Procedure for Determination of Phthalates as a guide

Test Results

Composition: (parts per million, mg/kg)

Identification	DnHP‡	DnBP‡§	BBP‡§	DEHP‡§	DnOP§	DINP‡§	DIDP‡§
	1000 Max.	1000 Max.	1000 Max.	1000 Max.	1000 Max.	1000 Max.	1000 Max.
Top Surface	ND*	ND*	ND*	ND*	ND*	ND*	ND*
Bottom Surface	ND*	ND*	ND*	ND*	ND*	ND*	ND*

*N.D. – None Detected <50 ppm: Di-n-Hexyl Phthalate (DnHP) Di-n-Butyl Phthalate (DnBP), Butyl Benzyl Phthalate (BBP), Di-Ethyl Hexyl Phthalate (DEHP), Di-n-Octyl Phthalate (DnOP), Di-Isononyl Phthalate (DINP) and Di Isodecyl Phthalate (DIDP)

§CPSIA Subsection 108(a) requirement for phthalates

‡CA Prop 65 requirements for phthalates

Prepared by: M. M. Tippens M. M. Tippens
Chemist

Approved by: P. E. Rogers P. E. Rogers
Manager



This report may not be reproduced except in full without the written approval of ATS. This report represents interpretation of the results obtained from the test specimen and is not to be construed as a guarantee or warranty of the condition of the entire material lot. If the method used is a customer provided, non-standard test method, ATS does not assume responsibility for validation of the method. Measurement uncertainty available upon request where applicable.